

Controlling Exposures to prevent occupational lung disease in the construction industry



## **HAZARDS AND RISKS**

Specialist plant operatives using excavators, bulldozers, graders, loaders, dumper trucks and piling/drilling machinery etc. to carry out demolition, excavate or move construction materials and waste about site can be exposed to many different harmful substances.

### Dusts

Dust is generated when moving materials around constructions sites, as well as during piling and drilling operations. Dust inside the driver cabs can dry out and become airborne when disturbed. The risk may be greater on derelict or contaminated land sites where hazardous substances such asbestos, silica, toxic metals and organic matter, such as animal droppings, may be present.

### Gases, fumes and vapours

Operation of plant and machinery can result in exposure to high levels of diesel engine exhaust emissions (DEEEs), particularly in confined spaces. Gases and vapours may arise where work involves disturbance of sludges. Work in confined spaces such as drainage or sewer structures (particularly on derelict sites) might also result in exposure to gases such as hydrogen sulphide.

## Risks to health

Breathing in these hazardous dusts, gases and vapours can cause serious, debilitating, irreversible, life-limiting, and, in some cases, fatal illnesses, which include lung cancer, pulmonary fibrosis (eg. asbestosis/silicosis), asthma, pulmonary oedema and chronic obstructive pulmonary disease (COPD). DEEEs contain a complex mix of gaseous components and particulates. DEEEs may cause respiratory tract irritation and have also been linked to long term increased risk of lung cancer.

## **CONTROL OPTIONS**

## **Control measures**

As there are so many airborne pollutants to which a plant operator may be exposed, it is vitally important that exposure risk assessments are completed for all activities to identify the significant risks and appropriate control measures. The findings should be communicated to ensure that they are understood by any worker who may be at risk. A qualified occupational hygienist or occupational hygiene technologist can assist with the exposure risk assessment, to help to identify exposures to hazardous substances,

## **CONTROL OPTIONS**

advise on the level of exposure risk and select the appropriate control measures – particularly where work is carried out on contaminated land or derelict sites. These measures should be task specific, and developed following a hierarchy of control which should start with preventative measures, followed by engineering controls and working methods and then consider PPE as a last resort.

### **Elimination/prevention**

 In general, plan work so that operatives are located away from plant or tasks that generate dust; remote operation of plant is preferable.

#### DEFE

- Substitute diesel plant for safer alternative eg. electric motors.
- Warm up diesel engines outside before entering confined areas, and do not leave engines idling.
- Ensure good engine maintenance.

# Engineering controls Dusts

- Rock drills, piling rigs etc. should feature integrated water dust suppression systems.
- Local exhaust ventilation (LEV) should be used to extract airborne dust before it can be breathed in. The most effective types of LEV are generally those that are integrated into plant.

### DEEES

 Fit catalysts/particulate traps to vehicle exhausts.

### General

- Use exhaust extraction to remove fumes to a safe place outside.
- Ventilated, closed cabs are one of the most effective measures for lowering exposures.

# Safe working methods DEEEs

 All working areas must be well ventilated, particularly where diesel plant or internal combustion engines (e.g. on compressors or generators) operate.

### PPF

PPE should be a last resort control measure as it has to be worn properly all of the time, and it does not "fail safe". It needs to be carefully selected to ensure it provides adequate protection. Tight fitting respiratory protective equipment (RPE) must be face fit tested to ensure that it affords the anticipated level of protection for each individual. RPE selection should be made in line with the risk assessment and selected in accordance with CSA Z94.4-11 Selection, Use and Care of Respirators.

#### Dust

- Minimise the height through which deposited materials fall to reduce the dustiness of a job – particularly during windy conditions.
- Apply water to cutting/drilling work, and on dusty thoroughfares over which vehicles travel.
- Dustless cleaning techniques such as vacuuming of cabs and wet cleaning of plant should be used; avoid using compressed air to clean dust from plant or personal work-wear.
- A high standard of internal cab cleanliness is important to prevent accumulation of dust which can be breathed in when disturbed.
   During work on contaminated sites entry to and from a cab may need to be restricted to a "clean" zone to prevent contamination. Seats should feature an impermeable cover to prevent dust penetration and facilitate cleaning.

# MANAGING THE RISK

Training & communication, supervision, maintenance & testing of controls and air

monitoring\* are all vital aspects of managing the risk, in addition to health surveillance which can be a requirement in certain circumstances.

See our introductory Respiratory Health Hazards in Construction Fact Sheet Series: **Overview** for more information about what things to consider and implement.

## Air monitoring\*

Air monitoring is a specialist activity. It may be needed as part of an exposure risk assessment, as a periodic check on control effectiveness and to assess compliance with relevant occupational exposure limits, or where there has been a failure in a control (for example if a worker reports respiratory symptoms).

A qualified occupational hygienist or occupational hygiene technologist can ensure exposure monitoring it is carried out in a way that provides meaningful and helpful results.

### **Further information**

Other fact sheets in this series cover specific construction trades, associated respiratory health risks and appropriate control options.